



Risk Management and Safety Outsourcing

The task of performing audits, inspections, and recertifications required by the Process Safety Management (PSM) and Risk Management Program (RMP) regulations is frequently neglected. The daily workload of engineering and maintenance personnel, along with their usual conviction that repairs and maintenance have priority, results in programs of the US Environmental Protection Agency (EPA) and Occupational Safety and Health Administration (OSHA) programs being put "on the shelf." When OSHA, EPA, or other regulatory agencies inspect your facility and documentation of required programs, huge fines can be assessed for being out of compliance.

SCS Tracer has more than 50 years of combined experience and direct involvement in preparing and implementing OSHA and EPA type programs required of facilities that have large ammonia refrigeration systems. We employ a staff that is fully trained and has the experience necessary to bring clients into and maintain compliance with governmental regulatory agencies for their ammonia-refrigerated facilities.

Our Risk Management and Safety Outsourcing Practice

Process Safety Management (PSM):

- Compliance audits.
- Mechanical integrity inspections.
- Standard operating procedures (SOPs) and annual certification.
- PHA revalidations.
- Recommendation tracking.

Risk Management Program (RMP):

- Hazard assessment: 5-year revalidations.
- EPA RMP submittals: 5-year resubmittals.
- State-specific submittals and updates.
- EPA audit preparation.
- Contractor packages.